


Geared Grip Tape Dispenser



1-Install the double sided grip tape roll onto spool #1 as shown.


2-Pull approximately 6" of tape and pull the backing off to spool #3

3-Pass the double sided tape over Spool #2 and on top of the blade


4-Pull the tape backing to the bottom and around spool #3 and thread the backing through the slit.

5- Rotate Spool #1 anti-clockwise to take out the slack and ensure proper threading.


Please note that the tension is Spool #1 and Spool #3 can be adjusted by tightening the thumb screws as needed.



Pull grip tape downward with a steady hand so that the grip tape drags over the metering spool #3... Until the spools lockup...



Rip the grip tape over the blade from the inner to the outer edge while pressing down in a swift and deliberate action. The blade holder will automatically collapse, resetting the spools for the next grip tape strip.



Dispensing tape:
Lift tape off the blade...